

July 11, 1983

Mr. Tom Tetting Engineering Geologist State of Utah 4241 State Office Building Salt Lake City, Utah 84114

Dear Tom,

RE: South Lisbon Act/037/018 San Juan County, Utah

In response to your letter dated June 13, 1983, I made a physical inspection of the area in question on June 22, 1983. As you may recall in a telecon I had with you on 6/20/83, I was somewhat surprised that the revegetation was not doing well around the SL-1 pit, since it seemed to be doing well at the portal area etc.

After my inspection of this area, my conclusions seem to concur with yours. I feel that the revegetation efforts around the portal and stockpile areas however, is progressing nicely. I have instructed our field personnel to re-do the area to the southwest and northwest of the SL-1 pit in late fall, 1983. We will use the same seed mixture as before as well as the same planting procedure. The only exception would be to concentrate on dragging the area more than before, however the limited topsoil may not allow this.

I will keep you advised as to our progress, which hopefully will be more productive the second time around.

> Sincerely yours, MINERALS RECOVERY CORPORATION

(Mrs.) Dianna D. Assistant Vice President

de/ms

cc: D Stucker

E Limberg

DIVISION OF OIL GAS & MINING